PREPARED IN COOPERATION WITH THE
STATE OF WISCONSIN DEPARTMENT OF NATURAL RESOURCES
AND
UNIVERSITY EXTENSION, UNIVERSITY OF WISCONSIN
GEOLOGICAL AND NATURAL HISTORY SURVEY



Figure 12.–Map showing locations of stream-gaging stations, measuring sites, and check dams; profiles for the gaged streams; and graphs showing flow at all sites during five periods of dry weather in 1964, 1965, and 1966 in part of the sand plain area of central Wisconsin.